



Don Thompson 2318 SE Thornwood Drive Lindenhurst, Ill. 60046

home phone – **847-356-5080** cell phone – **847-533-5080**

1960 Evans SPL engine(s) – **Mc-9**

muffler/pipe – **Header** carburetor(s) – **2 Flatbacks**

clutch type – **Max Torque**

tire size- front – **4.10-3.50x5** rear – **4.10-3.50x6**

brakes – **Scrub**

where found? – **Sale paper** original? restored? being restored? -**Restored**

initial cost?- **\$300** cost to restore? - **\$500** how long to restore it? - **4 months**

condition when received or found? - **Poor**

what other karts do you have? - **40+ sprint karts**

what are you working on now? – **SAE kart**

did you race in the past? - **No**

what parts are you still looking for? – **Rathman fuel tank, Hornet sprint tank**

how far did you travel to get to TBO? – **from N. Ill.**

how many events attended each year? - **2**