



**Robert (Bobby) Hartman 205 Vicki Lane**  
 home phone – **419-435-7444** cell phone – **419-597-6117**  
 email – **kartman17@earthlink.net**  
 chassis (year, model if known) – **1961 Lancer** engine(s) – **(2) Power Products 58s**  
 muffler/pipe – **Azusa stacks** carburetor(s) – **Tillotson**  
 clutch type – **MaxTorque** no. teeth – **10** no. teeth axle sprocket - **68**  
 tire size- front – **4.10 x 5** rear – **6.00 x 5** brakes – **Twin MCP dual calipers**  
 where found? – **Family kart** original? restored? being restored? - **Restored**  
 initial cost? - cost to restore? - **\$1000** how long to restore it? – **6 months**  
 condition when received or found? – **Broken frame at steering hoop**  
 did you race in the past? – **Yes**  
 where? – **Hasselback, Port Clinton (dirt), Tiffin (dirt)**  
 how far did you travel to get to TBO? – **25 miles**